

March 17, 2017

Sharon Butts, Director Cadiz Trigg County Economic Development Commission 5784 Hopkinsville Road Cadiz, KY 42211

RE: ASTM E1527-13 Phase 1

Environmental Site Assessment Process Tract 2 including Invest Prep Project Interstate 24 Business Park

Dear Mrs. Butts:

Ronald Johnson and Associates, P. S. C. (RJA) has conducted a Phase I Environmental Site Assessment (ESA) of the above referenced property. This ESA uses the ASTM E1527-13 Phase 1 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process in order to complete a more efficient due diligence effort.

The purpose of RJA's investigation was to conduct an appropriate inquiry to obtain commonly known or reasonably ascertainable information about the property with respect to the presence or likely presence of hazardous or toxic contamination at the site. Our Phase I ESA specifically consisted of interviews with personnel noted in this report and various state and federal agencies database's were accessed for information concerning the review site.

RJA's inspection was conducted only to determine the obvious presence or likely presence of contamination of the property and to identify when possible, environmental compliance issues. This document should not be construed as a guarantee or assurance that undiscovered environmental problems do not exist.

If you have any questions or if I can be of further assistance, please feel free to contact me at (270) 821-6392 ext. 206.

Sincerely,

Bruce DiPasquale

Senior Project Manager

Bruce Di Pasquale

File

ASTM PHASE 1 ENVIRONMENTAL SITE ASSESSMENT REPORT

PREPARED FOR

Cadiz – Trigg County Economic Development Commission 5748 Hopkinsville Road Cadiz, KY 42211

PERFORMED AT

INTERSTATE 24 BUSINESS PARK
Tract 2
Including
INVEST PREP PROJECT

By

Ronald Johnson & Associates, P.S.C. 24 West Center Street Madisonville, Kentucky 42431

MARCH 17, 2017

TABLE OF CONTENTS

| SECTIO | PAGE | |
|--------|------------------------------|----|
| 1. | EXECUTIVE SUMMARY | 1 |
| 2. | INTRODUCTION AND LIMITATIONS | 2 |
| 3. | SITE DESCRIPTION | 3 |
| 4. | USER PROVIDED INFORMATION | 4 |
| 5. | RECORDS REVIEW | 6 |
| 6. | SITE RECONNAISSANCE | 9 |
| 7. | INTERVIEWS | 11 |
| 8. | CONCLUSIONS | 12 |
| 9. | RECOMMENDATIONS | 12 |
| 10. | DEVIATIONS | 12 |
| 11. | ADDITIONAL SERVICES | 13 |
| 12. | REFERENCES | 13 |
| 13. | CERTIFICATION | 14 |
| 14. | QUALIFICATIONS | 14 |

FIGURES

APPENDICES

| Appendix A | PVA and Deed information |
|------------|--|
| Appendix B | Aerial Photos |
| Appendix C | EDR Report/Regulatory Data |
| Appendix D | Questionnaire |
| Appendix E | Historic Topographic Maps |
| Appendix F | City Directories |
| Appendix G | Environmental Professional's Qualifications |

1 EXECUTIVE SUMMARY

Ronald Johnson and Associates, PSC (RJA) was contracted by Sharon Butts, Director of Cadiz Trigg County Economic Development Commission to perform a Phase I Environmental Site Assessment (ESA) Report for vacant property located in Tract 2 within the Interstate 24 Business Park Cadiz, KY 42211. This report is inclusive of subject property and those remaining properties in Tract 2 (adjacent properties) totaling 83 acres, as seen on Figure 1. The Invest Prep Project Site is within Tract 2 and is referred to as the property in question or subject property. The subject property is a 15 acre tract subdivided from Tract 2, as seen on Figure 2. For anyone reviewing this report the use of the name "Interstate 24 Business Park" and "Industrial Park # 3" are one and the same.

RJA reviewed aerial photos, which documented the land use in 1949 as agricultural development and as of the date of this report remains in an agricultural land use.

The subject property was visited by RJA's representative, Mr. Bruce DiPasquale, on March 8, 2017. No one accompanied Mr. DiPasquale on the site walk through. The subject property appears to be agricultural land use. RJA saw no evidence of leaks or significant staining, dead or dying vegetation on the property that would indicate a release of toxic chemicals. No evidence of underground or aboveground tanks were observed from those vantage points. The concrete base for the 3 former grain silos are still apparent, an abandoned power pole is nearby and what appears to be a water well is obvious.

According to the Trigg County Joint Planning and Zoning Commission, the subject property is zoned Industrial. Due to the zoning classification there could be covenants / restrictions not referenced on the deed.

RJA conducted a review of regulatory search information prepared by Environmental Data Resources, Inc. (EDR). The search radii equaled or exceeded the criteria specified in ASTM E 1527-13. A regulatory records search of this nature is based on information published by State and Federal regulatory agencies, and is used to evaluate if the subject property or nearby properties are listed as having a past or present record of actual or potential environmental impact. Please note that regulatory listings include only those facilities that are known to the regulatory agencies at the time of publication. The EDR report, dated February 14, 2017, is presented in Appendix "C". The EDR reports reference "Industrial Park # 3" however the official name of the industrial park is "Interstate 24 Business Park. The subject property or the adjacent properties were not listed on any environmental database as having past, present or pending enforcement issues or any active or inactive environmental permits, relating to hazardous chemicals.

RJA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E 1527-13 for the property in question. Interstate 24 Business Park is located along US Hwy 68/80 and KY Hwy 276 /Rocky Ridge Road. Any exceptions to, or deletions from, this practice are described in Section 10 of this report. Based on the results of our review of an environmental and regulatory database search, review of regulatory agency records, and site reconnaissance, our findings and conclusions of this assessment are as follows:

- Recognized Environmental Conditions (REC) for the subject property were not discovered in preparing this report.
- Other conditions exist that are outside the scope of an ASTM Phase 1 Report, but must be called to the attention of the user(s). These conditions if they exist would be related to karst geology, water well closure.

Based on these findings, RJA does not recommend that a Phase II Environmental Site Assessment (ESA) be conducted at the subject property.

2 INTRODUCTION AND LIMITATIONS

This Phase I ESA Report complies with the All Appropriate Inquiries Rule set forth and codified by the United States Environmental Protection Agency on November 1, 2005. The Phase I ESA Report has been prepared in accordance with the new American Society of Testing and Materials (ASTM) Standard E-1527-13. As specified in this standard, certain responsibilities lie with the "user" of the assessment. The "user" is defined as the party who intends to use the ASTM guidance to perform an assessment. The "user" is generally the purchaser, owner, lender, property manager, or potential tenant. Under the ASTM standard, it is the responsibility of the "user" to verify whether any environmental liens exist with regard to the subject property, and provide this information to the environmental professional preparing the assessment. Additionally, the "user" must make the professional aware of any specialized knowledge or experience that is material to Recognized Environmental Conditions (RECs) in connection with the subject property. Information provided in this regard is presented in the Records Review section of this report.

RJA's work was performed consistent with that level of care and skill ordinarily exercised by members of the profession currently practicing in the same locality under similar conditions. Information provided to RJA by client representatives and site contacts has been accepted in good faith and is assumed to be accurate. RJA's findings are based on observations and data collected at one point in time.

Assessment results are based upon conditions and operations at the time of the site visit. A change in any of these factors may alter the findings and conclusions expressed by RJA.

It should be understood that a site walk through, by nature, is limited in its ability to fully assess potential environmental liabilities associated with any real estate transaction. Further investigation would be required to identify potential environmental liabilities, which may be present at the site, but were beyond the scope of this Phase I Environmental Assessment. State and federal laws and regulations referenced in this report are provided for information purposes and should not be construed as legal opinion or recommendation.

This report has been prepared solely for the reliance of the entity identified as "Prepared For" on the front cover of this ESA report. Neither all nor any part of the contents of this report shall be reproduced, conveyed, or relied upon by any means to parties other than the entity indicated with the express written consent of Ronald Johnson & Associates, P.S.C.

2.1 User Reliance

This report is the work product of RJA, which has been produced in accordance with a specific contract between RJA and its Client, who is represented by the party to whom this report is addressed. This report is the work product for the sole use and benefit of the contracting Client. It does not create any rights or benefits to parties other than the Client and RJA, except such other rights as are specifically called for herein.

Any use of, or reliance upon, this information by a party other than the Client, shall be solely at the risk of such third party and without legal recourse against RJA, its affiliates, associates, employees, officers, or directors, regardless of whether the action in which recovery of the damage is sought is based upon contract, tort (including the sole, concurrent or other negligence and strict liability of RJA), statute or otherwise. This report shall not be used or relied upon by a party, which does not agree to be bound by the above statement. This report is valid as of the date shown and RJA shall not be held responsible for subsequent changes in Physical/Chemical/Environmental conditions and/or legislation over which RJA has no control.

3 SITE DESCRIPTION

3.1 Location and Legal Description

The Subject Property is located within Interstate 24 Business Park near US Hwy 68/80 and KY Hwy 276 Cadiz, Kentucky 42211. The subject property is located at Latitude 36.88181⁰ North and Longitude -87.74866⁰ West. See Appendix "A". The owner has provided a legal description of the area and it is included in Appendix "A" of this report.

3.2 Site and Vicinity General Characteristics

The subject property is a developing industrial park. One industry has located in the park as of the date of this report. Within the park, the vacant land, including the subject property is used for row crop production. Surface water runoff flows to nearby sink holes.

RJA accessed the FEMA flood maps and determined that the subject property is not in a flood plain. A copy of the FEMA flood map is not in this report.

3.3 Current Use of the Property

Currently the property in question is vacant land used for agriculture.

3.4 Descriptions of Structures, Roads, other Improvements

The subject property is accessed from US Hwy 68/80 and KY 276. The area has city water and sewer, TVA electric service and ATMOS Energy for natural gas service. There are no structures on the property or on adjacent properties. There are no other improvements to discuss.

3.5 Current Uses of the Adjoining Properties

RJA noted that the subject property is found completely within the business park property with no adjoining properties as of the date of this report. Transcraft, a truck trailer producer is located across the street from the subject property. Outside the business park are a variety of commercial businesses including agriculture.

4.0 USER PROVIDED INFORMATION

Mrs. Butts provided a map of the subject property and explained important features of the map. See Figure 2.

The Phase I questionnaire pertaining to ownership and potential environmental liens was completed by Mrs. Butt's with the assistance of Mr. Bruce DiPasquale. See Appendix D. The questionnaire did not reveal any new information because Mrs. Butts does not have firsthand knowledge of land use history for the subject property or adjacent property.

RJA was given permission from the owner to contact Mr. Scott Jolly, a former owner of the subject property. RJA interviewed Mr. Jolly, see Section 7.4.

4.1 Title Records

A Title Report was not otherwise available as of the date of this report and the client did not request that RJA order one as part of the scope of work for the Phase I. According to Mrs. Butts, the Cadiz Trigg County Economic Development Commission owns all the property within the industrial park, including the subject property.

4.2 Environmental Liens or Activity and Use Limitations

Based on the attached questionnaire, see Appendix D, Mrs. Butts is not aware of any environmental liens. She is not aware of any activity/use limitations (AULs), conveyances or deed restrictions associated with the subject property other than those imposed by the industrial zoning classification.

4.3 Specialized Knowledge

Mrs. Butts does not have specialized knowledge of the subject property while in the active agricultural life of the subject property. Mrs. Butts did schedule a meeting with the former owners of the subject property for an interview, which is discussed in Section 7.4. Mrs. Butts is not aware of any environmental condition(s) as defined by ASTM for property undergoing a Phase 1 review.

4.4 Commonly Known or Reasonably Ascertainable Information

Based on the interview with Mrs. Butts, she informed RJA that he has no knowledge regarding the past use of the property as it relates to recognized environmental conditions such as specific agricultural chemicals, spills, or environmental cleanups on the subject property.

4.5 Valuation Reduction for Environmental Issues

RJA has not been asked to provide this information.

4.6 Owner, Property Manager, and Occupant Information

According to the Trigg County Property Valuation Administrator (PVA), the Cadiz Trigg County EDC (Owner) has owned the subject property since 1992.

4.7 Reason for Performing Phase I

The reason for performing this Phase I report is due diligence associated with a potential real estate transaction.

4.8 Other

Based on an interview, Mrs. Butts has no additional information regarding the subject property to provide RJA.

5 RECORDS REVIEW

5.1 Standard Environmental Record Sources (Regulatory Database Research)

RJA conducted a review of regulatory search information prepared by Environmental Data Resources, Inc. (EDR). The search radii equaled or exceeded the criteria specified in ASTM E 1527-13. A regulatory records search of this nature is based on information published by State and Federal regulatory agencies, and is used to evaluate if the subject property or nearby off-site properties are listed as having a past or present record of actual or potential environmental impact. Please note that regulatory listings include only those facilities that are known to the regulatory agencies at the time of publication. The EDR report dated February 14, 2017 is presented in Appendix C. The data base search report is 74 pages and only the summary findings are presented in this report. Enclosed in Appendix C is an electronic copy of the full EDR report.

The subject property is not listed in the EDR report as having any environmental documentation relating to recognized environmental conditions as defined by the ASTM standard.

5.2 Regulatory Agency Record Sources

A state regulatory agency interview was conducted with the Kentucky Department of Environmental Protection Waste Management Division, and the Kentucky Department of Environmental Protection Division of Water.

According to the Kentucky Department of Environmental Protection Division Waste Management (KDWM), the subject property has no record of past, present or pending enforcement actions.

The Kentucky Department of Environmental Protection Division of Water records there are no past, present or pending enforcement actions on the subject property.

5.2.1 Local Agency Sources

RJA contacted the Trigg County Health Department – Environmental Section and the Cadiz Fire Department and determined there were no environmental records for the subject property.

5.3 Physical Setting Source(s)

5.3.1 Regional Geology

The subject property is located on the south central limit of the Mississippian Plateau Physiographic Region of Kentucky. According to the Cobb and Gracey, Kentucky Geologic Quadrangle Maps the subject property is underlain by the Mississippian Aged St. Genevieve Limestone and Upper Member of the St. Louis Limestone, undivided. These formations are primarily a white, oolitic limestone. Solution features such as caves, sinking streams, and sink holes are common. Based on review of the GQ, geologic faulting was not indicated under or near the subject property.

5.3.2 Surface Water Characteristics

Topography of the area surrounding the site is gently rolling and considered a karst topography. Surface drainage for the subject property is controlled and drains primarily into karst features. The subsurface drains generally in a westward direction and discharges into Little River via a spring located in the City of Cadiz. No blue line streams are located within the immediate vicinity of the subject site.

5.3.3 Ground Water Characteristics

Ground water occurs in the unconsolidated sediments and underlying limestone around the general area, although its availability is variable both laterally and vertically. Ground water flow is generally to the west. Most of the drilled water wells in this area yield enough water for a domestic supply with a pump. Wells penetrating large solution channels can produce from 5 gallons to 50 gallons per minute. The subject property does not lie in the Well Head/Spring Protection Zone established by the City of Cadiz, but is adjacent to the protection area, see Figure 3.

5.4 Historical Use Information on the Property and Adjoining Properties

5.4.1 Oil and Gas Map

According to the Kentucky Geologic Data Base on oil and gas wells, there are no oil or gas wells on or near the subject property.

5.4.2 Historical Topographic Maps

EDR obtained historical topographic maps for this Phase 1 report. United States Geological Survey (USGS) Gracey 7.5-Minute Quadrangle topographic maps were reviewed for this ESA. The USGS map provides no new information on the subject property. The maps are dated 1951, '53, '67, '74, '83, '82, '81 and 2013. See Appendix E.

5.4.3 Sanborn Fire Insurance Map Research

Sanborn Fire Insurance Maps (Sanborn Maps) do not exist for this location.

5.4.4 City Directories Research

EDR searched available City Directories to determine if the address for the subject property appeared as a business address. The subject property does not appear in any City Directories. See Appendix F.

5.4.5 Trigg County Property Valuation Administration

Trigg County PVA property information is found in Appendix A and illustrate the subject property. No new information was obtained based upon the review of the PVA information.

5.4.6 Aerial Photograph Research

Available aerial photographs for the subject property and vicinity were obtained from EDR and Google Earth. A total of sixteen aerial photographs were reviewed for this Phase 1 report. See Appendix B.

The EDR and Google Earth aerial photos depict a history of the subject property and the adjacent properties. The subject property is clearly seen as farmland in the 1949 thru the 2015 photos. Upon close examination of the photos and the site walk through it is possible to locate the concrete bases for the grain silos. The walk through revealed the location of the former groundwater well as immediately west of the western most concrete silo pad.

RJA's review of the historical and more recent aerials did not reveal any features that would indicate spills or release of chemicals that would cause surface staining.

RJA cannot be sure of what might have happened on the property before, between or after the dates of these photos.

5.5 Previous Environmental Reports

There was one previous environmental report for the subject property written in 2002.

A more recent report, although not an environmental report as defined by ASTM, was written in 2014, regarding subsurface conditions as they relate to the Karst geology of the area. This "Preliminary Geophysical Investigation of I-24 Business Park" is not discussed herein or attached to this report.

6 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

RJA's work was performed consistent with that level of care and skill ordinarily exercised by members of the profession, currently practicing in the same locality under similar conditions. Information provided to RJA by client representatives and site contacts has been accepted in good faith and is assumed to be accurate. RJA's findings are based on observations and data collected at one point in time. Assessment results are based upon conditions and operations at the time of the site visit. A change in any of these factors may alter the findings and conclusions expressed by RJA.

It should be understood that a site walk through, by nature, is limited in its ability to fully assess potential environmental liabilities associated with any real estate transaction. Further investigation would be required to identify potential environmental liabilities, which may be present at the site, but were beyond the scope of this Phase I Environmental Assessment.

State and federal laws and regulations referenced in this report are provided for information purpose and should not be construed as legal opinion or recommendation. Use and distribution of this document is limited to RJA's client and those parties identified for distribution by the client.

6.2 Site Walk Through

6.3.1 Observations

During the walk through RJA did not attempt to locate the exact property corners. The subject property and remaining portions of Tract 2 are cultivated for row crops and survey pins are most likely gone due to soil disturbance caused by cultivation. RJA made observations from various vantage points and on foot. RJA saw no evidence of chemical or oil spills, no evidence of stained soil or dead or dying vegetation due to spills or releases of hazardous or toxic chemicals on the subject property. RJA saw no evidence of above ground or underground storage tanks. RJA saw no accumulation of used batteries, tires, hazardous or toxic substances on the property.

The subject property (Invest Prep Project Site) is entirely cultivated for row crops. Adjacent to the subject property and near the eastern lot line are visible structures (the concrete pads for the former grain silos, a power pole and a groundwater well) remaining from the earlier farm activities. The adjacent properties north of the subject property are used for agriculture and one commercial property (One Church 526 N. Rocky Ridge Road), east is agricultural, south is Highway 68/80 and commercial properties and west is agricultural land use.

6.3.2 Polychlorinated Biphenyls (PCBs)

RJA did not see any electrical transformers on the subject property.

6.3.3 Pesticides

No pesticides or herbicides were observed being stored or used at the subject property.

6.3.4 Endangered Species

According to the US Fish and Wildlife Service website there are endangered species in Kentucky and in Trigg County. RJA did not attempt to physically locate or identify endangered species on the subject property. This property is currently farm land property. It is not likely endangered species would be found on the property.

7 INTERVIEWS

RJA interviewed five individuals with varying knowledge of the property in question to determine a history of land use and environmental practices. RJA talked with Shannon McLeary - Kentucky Division of Water Enforcement Supervisor and Amber Stewart, Inspector with the Kentucky Division of Waste Management and Mrs. Sharon Butts, Cadiz Trigg County EDC Director and Mr. Scott Jolly, former owner.

7.1 Interview with Owner's Representative

Mrs. Butts indicated that she has no current or past knowledge of farm activities on the subject property or the remaining area in Tract 2. Mrs. Butts had no additional information to provide regarding the past use of the property.

7.2 Interview with Kentucky Division of Waste Management

RJA interviewed Amber Stewart, Inspector for the Kentucky Division of Waste Management and was informed that there are on records of enforcement actions or permits for the subject property in their files. Ms. Stewart indicated that the industrial property across International Drive, Transcraft currently has no past, present, pending enforcement actions.

7.3 Interview with Kentucky Division of Water

RJA interviewed Shannon McLeary, Supervisor, with the Division of Water. Ms. McLeary indicated that the subject property or adjacent properties have no record for enforcement actions.

7.4 Interview with Scott Jolly, former Owner

RJA interviewed former owner of the subject property and the remaining properties in Tract 2. Mr. Jolly owned the property from 1992 to 2006 when it was sold to Cadiz Trigg County Economic Development Commission. Mr. Jolly, prior to his ownership, recalls the property was used for pasture land and was not cultivated. Mr. Jolly cultivated the property during his ownership and did not use the grain silos. He recalled the buildings and grain silos were removed in 2001. Mr. Jolly as of the date of this report continues to cultivate the property. When asked about his crop management he remarked that he always hired a company to custom apply any herbicides or pesticides. During his ownership there were no chemicals stored on site and no above or below ground fuel tanks. He was not sure of past agrichemical usage.

8 CONCLUSIONS

RJA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E 1527-13 for property located in Tract 2 within the Interstate 24 Business Park Cadiz, KY 42211. Any exceptions to, or deletions from, this practice are described in Section 10 of this report. This assessment has revealed no evidence of recognized environmental conditions in connection with the subject property as they relate to the ASTM standard.

Based upon the information available the subject property has only limited environmental risk. This document should not be construed as a guarantee or assurance that undiscovered environmental problems do not exist.

9 **RECOMMENDATIONS**

Based on these findings, RJA recommends no further environmental investigations regarding the subject property.

9.1 Non-Scope Recommendation

There are non-scope conditions that may warrant consideration by the users of this report. The ground water well located adjacent to the grain silo concrete pad should be properly abandon per the Kentucky Division of Water regulations.

10 DEVIATIONS

This report adhered to ASTM Standard E-1527-13 and did not deviate from the standard, with the exception of the following:

Data Failure - No Sanborn Fire Insurance Maps

Data Failure - Business Directories only date to 1992.

Data Failure - A title opinion was not otherwise available for this report.

Data Gap – Historical Aerial photos only date to 1949.

In light of the other available information the data failures and gaps are not significant to the findings of this report.

The scope of this investigation was intended to provide selected environmental information in accordance with a scope of work contracted for by the Client/Owner.

The scope of work was not intended to be comprehensive, identify all potential concerns, or eliminate the possibility of the site having some degree of environmental problem. No degree of assessment can ascertain that a site is completely free of hazardous substances: some regulatory and other pertinent data may be lacking which is critical in completing a full environmental profile of the property. This report was compiled based partially on information from outside sources and other information, which is in the public domain. RJA makes no warranty as to the accuracy of the statements made by others which are contained in this report, nor are any other warranties or guarantees,

expressed or implied, included or intended in the report with respect to information supplied by outside sources, or conclusions or recommendations substantially based on information supplied by outside sources.

RJA's investigation, within the framework of the contractual scope of work, was performed using the degree of care and skill ordinarily exercised, under similar circumstances by reputable environmental specialists in this or similar localities. The report represents RJA's best professional judgment. Since the facts forming the basis for the report are subject to professional interpretation, differing conclusions could be reached. None of the work performed hereunder shall constitute or be represented as a legal opinion of any kind or nature. This report is issued with the understanding that it is the responsibility of the owner, or his representative, to ensure proper/legal disclosures to public, private and regulatory entities. The interpretations and recommendations of this report are based on the data collected and RJA's present working knowledge of environmental site assessments. As such, this report is valid as of the date shown and RJA cannot be responsible for subsequent changes in physical/chemical/environmental conditions and/or legislation over which RJA has no control.

11 ADDITIONAL SERVICES

RJA was not contracted to make conclusions in regard to archaeological, cultural, asbestos, radon, wetland delineation, surface or groundwater quality or quantity, geotechnical investigations, floodplain analysis, mold or lead-based paint. These issues are not part of the ASTM standard and were not included in the contracted scope of work.

12 REFERENCES

American Society of Testing & Materials Standard E-1527-13, <u>Environmental Site Assessments: Phase I Environmental Site Assessment Process</u> (November 18, 2005).

Environmental Data Resources, Inc. The EDR Radius Map Report

Trigg County PVA Office, Cadiz, Kentucky

United States Geological Survey, Gracey 7.5-Minute Quadrangle Map (1963).

University of Kentucky, Kentucky Geologic Survey – Kentucky Groundwater Data Repository, Water Well and Spring Location Map

University of Kentucky, Kentucky Geologic Survey – Kentucky Geologic Map Information Service – Oil and Gas Well Database

National Flood Insurance Program, Trigg County Kentucky Panel 140 of 375, Map Number 21221C0140C

13 **CERTIFICATION**

Report by:

Bruce Di Pasquale

14 QUALIFICATIONS

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental professional as defined in §312.10 of 40 CFR 312.

We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the All Appropriate Inquiries in conformance with the standards and practices set forth in 40 CFR Part 312. See Appendix G for environmental professional's qualifications.






FIGURE 1 CADIZ TRIGG COUNTY EDC

3-16-17 DRAWN BY: JBP


PPROVED BY:

CADIZ, KENTUCKY

RONALD JOHNSON & ASSOCIATES, P.S.C. CONSULTING ENGINEERING - LAND SURVEYING ENVIRONMENTAL CONSULTING - CONSTRUCTION INSPECTION HAS I GENERIS SITUATION OF A WAS INSTRUCTED BY A WAS I GENERIS STRUCTION INSPECTION OF A WAS INCOME. STRUCT OF A STRUCT

PROJECT IL 17-029 FILE NAME: Figure 1.dwg





2/16/2017 10:53 AM 1 of 1

APPENDIX

" A "

Deed & Property Information

D-Mitsia LONGED FOR RECORD NT 9:20 A M

FEB 1 5 2001

PER FEE / TAX
TRIGG COUNTY
WANDA H, THOMAS, CLERK
BY / Half D.C.

RECORDED IN

PAGE 395

QUITCLAIM DEED

THIS DEED made and entered into on this 214 day of February, 2001, by and between TRIGG COUNTY INDUSTRIAL

DEVELOPMENT AUTHORITY of P. O. Box 312, Cadiz, Kentucky 42211,

Grantor, and CADIZ-TRIGG COUNTY INDUSTRIAL DEVELOPMENT AUTHORITY

of P. O. Box 312, Cadiz, Kentucky 42211, Grantee,

WITNESSETH:

That for and in consideration of \$1.00, the receipt of which is acknowledged, and the parties declare the fair cash value to be \$300,000.00, Grantor quitclaims to the Grantee, its successors and assigns in fee simple absolute, all its right, title, and interest, including dower and curtesy, in and to the following described real estate located in Trigg County, Kentucky:

<u>Legal Description</u>: Property located on the west side of Kentucky 276 approximately 0.2 mile north of US 68 just west of I-24.

BEGINNING at an iron pin set in the west side of Ky. 276, 25 feet from the centerline of existing pavement, and being S. 38 degrees 46' 43" E., 30.56 feet from the NE corner of the Harold Stallons property, and being the south line of a 30 foot right of way retained by Exchange Enterprises, Inc.; thence with said right of way of Ky. 276 S. 38 degrees 46' 43" E., 1313.55 feet to an existing iron pin; thence a new division line in the Exchange Enterprises, Inc.

property the following: S. 62 degrees 11'
11" W., 974.95 feet to an iron pin (set); S.
8 degrees 58' 59" E., 552.81 feet to an iron
pin set in the NE corner of a 40.00 acre
tract; thence with the north line of said
40.00 acre tract N. 87 degrees 38' 07" W.,
1138.91 feet to an iron pin (set), said iron
pin being the east (at this point) line of
previously mentioned 30 foot right retained
by Exchange Enterprises, Inc.; thence with
said right of way N. 8 degrees 58' 59" W.,
1310.41 feet to an iron pin (set); and N. 62
degrees 11' 11" E., 1465.12 feet to the
point of beginning, containing 60.00 acres,
according to survey of James T. Boren dated
November 19, 1997.

Source of Title: BEING the same real property conveyed to Trigg County Industrial Development Authority by deed dated February 6, 1998 from Exchange Enterprise, Inc. which is recorded in Deed Book 184, page 357, Trigg County Clerk's Office.

This conveyance was authorized at a lawfully held meeting of Grantor and the undersigned officers have full power and authority to convey the premises for Grantor.

This conveyance is subject to valid and enforceable easements, restrictions, and covenants of record including those for existing roadways and utilities and including the utility easement set out below and as shown on the plat which is attached and incorporated by reference as if set out in full.

This conveyance is subject to a perpetual utility easement which runs 15 feet on each side of the line bearing S. 62 degrees 11' 11" W. 974.95 feet to an iron pin; thence S. 8 degrees 58' 59" E. 552.81 feet to an iron pin; thence S. 8 degrees 58' 59" E. 1537.05 feet. Also an additional utility easement 15 feet on each side of the line dividing the 40 acre tract from the 60 acre tract which line is 1138.91 feet long.

Consideration Certificate: By their signatures, the parties to this transaction or their agents declare that the sales price shown above is the full consideration paid for the property. Grantee signs this deed to so certify. We understand that falsification of the stated consideration is a Class D felony subject to one to five years imprisonment and fine up to \$10,000.00.

TO HAVE AND TO HOLD the above-described real estate, with all the improvements and appurtenances belonging to appertaining, to the Grantee, its successors and assigns in fee simple absolute.

TRIGG COUNTY INDUSTRIAL DEVELOPMENT AUTHORITY, Grantor

CADIZ-TRIGG COUNTY INDUSTRIAL DEVELOPMENT AUTHORITY, Grantee

Name and Title CHAIRMAN BY: But CHAIRMAN BY: Name and Title)

STATE OF KENTUCKY) (
) (SCT.
COUNTY OF TRIGG) (

Subscribed, sworn, and acknowledged before me this day of February, 2001 by Ben L. Cundiff as Chaigman of Trigg County Industrial Development Authority, Grantor, on behalf of the Authority.

My commission expires: 9-22-03

Disa Sadler Notary Public STATE OF KENTUCKY SCT. COUNTY OF TRIGG

The consideration certification was subscribed, sworn, and acknowledged before me this 8 to day of February, 2001 by Ben L. Cundiff as Vice Chairman of Cadiz-Trigg County Industrial Development Authority, Grantee, on behalf of the Authority.

My commission expires: 9-22-03

The undersigned is the draftsman only of this document and is not the person responsible for closing this transaction and the parties agree that the draftsman will not be construed as a person required to report this transaction under IRC §5064(e) or other applicable law.

No party to this transaction requested the draftsman to perform a title search on the premises conveyed.

DRAFTSMAN NOT RESPONSIBLE FOR DESCRIPTION FURNISHED


I certify that this instrument has been prepared by WOODALL & QUINN, Attorneys at Law, 14 Court Place, P. O. Box 1549, Cadiz, Kentucky 42211.

H. B. QUINN

STATE OF KENTUCKY COUNTY OF TRIGG, SCT:

! WANDA H. THOMAS, Trigg County Clerk, do certify that the foregoing was on this day at 8: 20 A.m. Lodged in my office for record. Where upon I have recorded the same with this certificate in my said office in Book # 200 Page 355 Given under my hand this... 2001 CLERK

BHOOR



| 61-031.01 Owner Information | | 221350 | Printed 3/16/2017 10:21:08 AN | |
|--------------------------------|---------------------|----------------------|---------------------------------------|--|
| | | Property Information | | |
| CADIZ TRIGG COUN | TY IND DEV AUTH | Address | #Error | |
| | | Class | EXEMPT PROPERTIES | |
| P O BOX 1487 | | Deed | 200-381 | |
| CADIZ, KY 42211 | | Tax District | 01 | |
| OTID | 560510 | Last Sale | 0 | |
| | | Description | INDUSTRIAL PARK III 63.53A | |
| Last Sales Date: 02/15 | 5/2001 | Date Assessed | 01/07/2016 | |
| 2017 Assessment Inf | ormation | | | |
| COUN LAND : 762,36 | 0 COUN TOT : 762.36 | 50 | · · · · · · · · · · · · · · · · · · · | |


| Land Information | | | | | |
|------------------|---------|----------------|------------|--------------|---------|
| LOT SIZE | 0 | STREET/ROAD | SECONDARY | FLOOD TYPE | NONE |
| FRONTAGE | 0 | DRIVEWAY TYPE | UNIMPROVED | UTILITY TYPE | WATER |
| DEPTH | 0 | DRAINAGE TYPE | | SIDEWALKS | NO |
| ACREAGE | 63.53 | ZONING CODE | | SUB ID | 1 |
| NEIGHBOR TYPE | TYPICAL | SITE COND TYPE | GOOD | LAND VALUE | 762,360 |


| Sale Information | | | | | | |
|------------------|------------|----------------|----------|----------|-----------|--|
| Sale Date | Sale Price | Previous Owner | Deedbook | DeedPage | Sale Type | |

| 61-031.01.01 | 2213 | 51 | Printed 3/16/2017 10:21:50 AM | | |
|---------------------------------|---------------------------|------------------|-------------------------------|--|--|
| Owner Information | | Property Inform | Property Information | | |
| CADIZ TRIGG COUNTY IND DEV AUTH | | Address | 489 INTERNATIONAL DR | | |
| | | Class | EXEMPT PROPERTIES | | |
| P O BOX 1487 | | Deed | 239-270 | | |
| CADIZ, KY 42211 | | Tax District | 01 | | |
| OTID | 560510 | Last Sale | 8,050,000 | | |
| | | Description | 27.99 ACRES | | |
| Last Sales Date: 12/28/200 | 16 | Date Assessed | 01/07/2016 | | |
| 2017 Assessment Inform | ation | | | | |
| COUN LAND: 315,800 | COUN IMPR : 7,734,200 COL | N TOT: 8.050.000 | | | |

| - | - | _ | - | - |
|------|------|------|-------|----|
| COUN | LAND | : 31 | 5,800 | CC |

| Land Information | | | | | | |
|-------------------|--------------------|----------------|--------------------------|--------------|-----------|--|
| LOT SIZE | 0 | STREET/ROAD | SECONDARY | FLOOD TYPE | NONE | |
| FRONTAGE | 0 | DRIVEWAY TYPE | ASPHALT | UTILITY TYPE | ALL | |
| DEPTH | 0 | DRAINAGE TYPE | V | SIDEWALKS | NO | |
| ACREAGE | 27.99 | ZONING CODE | The second second second | SUBID | | |
| NEIGHBOR TYPE | TYPICAL | SITE COND TYPE | GOOD | LAND VALUE | 315,800 | |
| Commercial Improv | ement Information | | | | | |
| COMM TYPE | INDUSTRIAL | BSMT TYPE | NONE | SPRINKLERS | YES | |
| CONTRUCT TYPE | STEEL FRAME | COVER TYPE | METAL | FIRE ALARM | YES | |
| STORIES | 1 | ROOF PITCH | LOW | IMPR VALUE | 7,734,200 | |
| AREA | | HEATING | YES | IMPR ADDRESS | | |
| QUALITY TYPE | AVERAGE | COOLING | NO | TOTAL UNITS | | |
| YEAR BUILT | 2005 | OFFICE SQFT | 8250 | UNIT VALUE | | |
| EFFECT AGE | | MANUF SQFT | 180000 | RENT MONTHLY | | |
| BLDG COND TYPE | GOOD | BASEMENT SQFT | | | | |
| EXT TYPE | SOLID MASONRY | ASPH SQFT | 0 | | | |
| FOUND TYPE | POURED CONCRETE | CONCRETE SQFT | 0 | | | |






Scale: 1 inch = 200.0

Sale Information

| Sale Date | Sale Price | Previous Owner | Deedbook | DeedPage | Sale Type |
|------------|------------|---------------------------|----------|----------|-----------|
| 12/28/2006 | 8,050,000 | BENSON INTERNATIONAL, LLC | 239 | 270 | |



APPENDIX

" B "

Aerial Photos

Trigg County Industrial Park # 3 - Tract 2
International Drive
Cadiz, KY 42211

Inquiry Number: 4854218.9

February 15, 2017

The EDR Aerial Photo Decade Package



EDR Aerial Photo Decade Package

02/15/17

Site Name:

Client Name:

Trigg County Industrial Park # :

Ronald Johnson & Associates psc

International Drive Cadiz, KY 42211

24 West Center Street Madisonville, KY 42431

EDR Inquiry # 4854218.9

Contact: Bruce Dipasquale



Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

| <u>Year</u> | Scale | <u>Details</u> | Source |
|-------------|---------|--------------------------------|-----------|
| 2012 | 1"=500' | Flight Year: 2012 | USDA/NAIP |
| 2010 | 1"=500' | Flight Year: 2010 | USDA/NAIP |
| 2008 | 1"=500' | Flight Year: 2008 | USDA/NAIP |
| 2006 | 1"=500' | Flight Year: 2006 | USDA/NAIP |
| 1993 | 1"=750' | Flight Date: March 09, 1993 | USGS |
| 1988 | 1"=750' | Flight Date: April 05, 1988 | USGS |
| 1973 | 1"=500' | Flight Date: October 18, 1973 | USGS |
| 1966 | 1"=500' | Flight Date: March 19, 1966 | USGS |
| 1951 | 1"=500' | Flight Date: March 31, 1951 | USGS |
| 1949 | 1"=750' | Flight Date: November 04, 1949 | USGS |
| | | | |

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES. INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.




































APPENDIX

" C "

EDR Report with full report on attached CD Trigg County Industrial Park # 3 - Tract 2 International Drive Cadiz, KY 42211

Inquiry Number: 4854218.2s February 14, 2017

The EDR Radius Map™ Report with GeoCheck®



6 Amisirong Koad, 4th lico Shellon, C1 00464 Toff Frae: 800 352 0050 www.edmet.com

TABLE OF CONTENTS

| SECTION | PAGE |
|--|--------|
| Executive Summary. | ES1 |
| Overview Map. | 2 |
| Detail Map | 3 |
| Map Findings Summary | 4 |
| Map Findings. | 8 |
| Orphan Summary. | 22 |
| Government Records Searched/Data Currency Tracking | GR-1 |
| GEOCHECK ADDENDUM | |
| Physical Setting Source Addendum. | A-1 |
| Physical Setting Source Summary | A-2 |
| Physical Setting SSURGO Soil Map. | A-5 |
| Physical Setting Source Map. | A-11 |
| Physical Setting Source Map Findings. | A-13 |
| Physical Setting Source Records Searched | PSGR-1 |

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

INTERNATIONAL DRIVE CADIZ, KY 42211

COORDINATES

Latitude (North): 36.8810380 - 36° 52' 51.73" Longitude (West): 87.7480380 - 87° 44' 52.93"

Universal Tranverse Mercator: Zone 16 UTM X (Meters): 433336.8 UTM Y (Meters): 4081734.0

Elevation: 518 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 5940235 GRACEY, KY

Version Date: 2013

Southeast Map: 5940471 CALEDONIA, KY

Version Date: 2013

Southwest Map: 5940469 CADIZ, KY

Version Date: 2013

Northwest Map: 5940475 COBB, KY

Version Date: 2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from: 20140705

Source: USDA

MAPPED SITES SUMMARY

Target Property Address: INTERNATIONAL DRIVE CADIZ, KY 42211

Click on Map ID to see full detail.

| MAP | | | | RELATIVE | DIST (ft. & mi.) |
|-----|----------------------|----------------------|-------------------|------------------|------------------|
| ID | SITE NAME | ADDRESS | DATABASE ACRONYMS | ELEVATION | DIRECTION |
| 1 | TRANSCRAFT CORPORATI | 489 INTERNATIONAL DR | RCRA-LQG | Higher | 963, 0.182, NW |

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

| Federal NPL site list | |
|---|--|
| NPL Nation Proposed NPL Prop NPL LIENS Fede | osed National Priority List Sites |
| Federal Delisted NPL site list | |
| Delisted NPLNatio | onal Priority List Deletions |
| Federal CERCLIS list | |
| FEDERAL FACILITY Federal SEMS Super | eral Facility Site Information listing erfund Enterprise Management System |
| Federal CERCLIS NFRAP site list | |
| SEMS-ARCHIVESupe | erfund Enterprise Management System Archive |
| Federal RCRA CORRACTS facility | ies list |
| CORRACTS Corre | ective Action Report |
| Federal RCRA non-CORRACTS T | SD facilities list |
| RCRA-TSDFRCR | A - Treatment, Storage and Disposal |
| Federal RCRA generators list | |
| RCRA-SQG RCR RCRA-CESQG RCR | A - Small Quantity Generators A - Conditionally Exempt Small Quantity Generator |
| Federal institutional controls / en | gineering controls registries |
| LUCIS Land US ENG CONTROLS Engi US INST CONTROL Sites | neering Controls Sites List |

| Federal | FRNS | list |
|---------|------|------|
| | | |

ERNS..... Emergency Response Notification System

State- and tribal - equivalent CERCLIS

SHWS..... State Leads List

State and tribal landfill and/or solid waste disposal site lists

SWF/LF...... Solid Waste Facilities List

State and tribal leaking storage tank lists

..... Facility Ranking List

INDIAN LUST Leaking Underground Storage Tanks on Indian Land SB193 SB193 Branch Site Inventory List

State and tribal registered storage tank lists

FEMA UST...... Underground Storage Tank Listing

UST______Underground Storage Tank Database INDIAN UST_____Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

ENG CONTROLS..... Engineering Controls Site Listing

INST CONTROL..... State Superfund Database

State and tribal voluntary cleanup sites

INDIAN VCP....... Voluntary Cleanup Priority Listing VCP........ Voluntary Cleanup Program Sites

State and tribal Brownfields sites

BROWNFIELDS..... Kentucky Brownfield Inventory

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS...... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY...... Recycling Facilities HIST LF..... Historical Landfills

INDIAN ODI_____Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL Delisted National Clandestine Laboratory Register

CDL..... Clandestine Drub Lab Location Listing

Local Land Records

LIENS 2 CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

SPILLS State spills

Other Ascertainable Records

RCRA NonGen / NLR RCRA - Non Generators / No Longer Regulated

FUDS...... Formerly Used Defense Sites DOD...... Department of Defense Sites

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing

US FIN ASSUR..... Financial Assurance Information

EPA WATCH LIST..... EPA WATCH LIST

2020 COR ACTION 2020 Corrective Action Program List

TSCA...... Toxic Substances Control Act

SSTS..... Section 7 Tracking Systems ROD......Records Of Decision RMP...... Risk Management Plans

RAATS...... RCRA Administrative Action Tracking System

PRP..... Potentially Responsible Parties

ICIS_____ Integrated Compliance Information System

Act)/TSCA (Toxic Substances Control Act)

...... Material Licensing Tracking System COAL ASH DOE..... Steam-Electric Plant Operation Data

COAL ASH EPA...... Coal Combustion Residues Surface Impoundments List PCB TRANSFORMER...... PCB Transformer Registration Database

RADINFO...... Radiation Information Database

HIST FTTS...... FIFRA/TSCA Tracking System Administrative Case Listing

DOT OPS...... Incident and Accident Data

CONSENT...... Superfund (CERCLA) Consent Decrees

INDIAN RESERV..... Indian Reservations

FUSRAP...... Formerly Utilized Sites Remedial Action Program

UMTRA...... Uranium Mill Tailings Sites

LEAD SMELTERS..... Lead Smelter Sites

US AIRS...... Aerometric Information Retrieval System Facility Subsystem

US MINES..... Mines Master Index File

FINDS_____Facility Index System/Facility Registry System

UXO...... Unexploded Ordnance Sites

DOCKET HWC...... Hazardous Waste Compliance Docket Listing

AIRS..... Permitted Airs Facility Listing COAL ASH....... Coal Ash Disposal Sites DRYCLEANERS..... Drycleaner Listing

Financial Assurance Financial Assurance Information Listing

LEAD..... Environmental Lead Program Report Tracking Database

NPDES______ Permitted Facility Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

| EDR MGP | EDR Proprietary Manufactured Gas Plants |
|------------------|--|
| EDR Hist Auto | EDR Exclusive Historic Gas Stations |
| EDR Hist Cleaner | EDR Exclusive Historic Dry Cleaners |

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

| RGA HWS | Recovered Government Archive | State Hazardous Waste Facilities List |
|---------|------------------------------|---------------------------------------|
| RGA LF | Recovered Government Archive | Solid Waste Facilities List |

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS


Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/12/2016 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

| Equal/Higher Elevation | Address | Direction / Distance | Map ID | Page | |
|------------------------|----------------------|--------------------------|--------|------|--|
| TRANSCRAFT CORPORATI | 489 INTERNATIONAL DR | NW 1/8 - 1/4 (0.182 mi.) | 1 | 8 | |

OVERVIEW MAP - 4854218.2S



ADDRESS:

LAT/LONG:

36.881038 / 87.748038

DATE: February 14, 2017 5:08 pm Copyright @ 2017 EDR, Inc. @ 2015 TamTom Rel. 2015.

CONTACT: Bruce Dipasquale INQUIRY #: 4854218.2s

APPENDIX

" D "

ASTM E1527-13 Questionnaire



X3. USER QUESTIONNAIRE

INTRODUCTION

In order to qualify for one of the Landowner Liability Protections (LLPs)¹⁸⁷ offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"), 188 the user must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by EPA Brownfield Assessment and Characterization grantees. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete.

| (1.) Environmental liens that are filed or recorded against the property (40 CFR 312.25). Did a search of recorded land title records (or judicial records where appropriate, seeNote 1 below) identify any environmental liens filed or recorded against the property under federal, tribal, state or local law? Note 1—In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that environmental liens and AULs be filed in judicial records rather than in land title records. In such cases judicial records must be searched for environmental liens and AULs. (2.) Activity and use limitations that are in place on the property or that have been filed or recorded against the property (40 CFR 312.26(a)(1)(v) and vi)). Did a search of recorded land title records (or judicial records where appropriate, seeNote 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law? Other where the property of the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as |
|--|
| records rather than in land title records. In such cases judicial records must be searched for environmental liens and AULs. (2.) Activity and use limitations that are in place on the property or that have been filed or recorded against the property (40 CFR 312.26(a)(1)(v) and vi)). Did a search of recorded land title records (or judicial records where appropriate, seeNote 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law? (3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as |
| vi)). Did a search of recorded land title records (or judicial records where appropriate, seeNote 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that age in place at the property and/or have been filled or recorded against the property under federal, tribal, state or local law? (3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as |
| (3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as |
| Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as |
| the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business? |
| for the baret file |
| (4.) Relationship of the purchase price to the fair market value of the <i>property</i> if it were not contaminated (40 CFR 312.29). Does the purchase price being paid for this <i>property</i> reasonably reflect the fair market value of the <i>property</i> ? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the <i>property</i> ? |
| (5.) Commonly known or reasonably ascertainable information about the property (40 CFR 312.30). Are you aware of commonly known orreasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, (a.) Do you know the past uses of the property? YES (b.) Do you know of specific chemicals that are present or once were present at the property? YES (c.) Do you know of spills or other chemical releases that have taken place at the property? None (d.) Do you know of any environmental cleanups that have taken place at the property? |
| (6.) The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31). Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property? No Visual prasence of contamination. 3-8-2017 - Scott Jolly, former owner + Bruce Diagnale consolidated this form. |
| this form. |
| 187 Landowner Liability Protections, or LLPs, is the term used to describe the three types of potential defenses to Superfund liability in EPA's Interim Guidance Regarding Criteria Landowners Must Meet in Order to Qualify for Bona Fide Prospective Purchaser, Contiguous Property Owner, or Innocent Landowner Limitations on CERCLE CRITICAL CRITIC |

- ding Liability ("Common Elements" Guide) issued on March 6, 2003. 188 P.L. 107-118.
- X3.1 In addition, certain information should be collected, if available, and provided to the environmental professional conducting the Phase I Environmental Site Assessment. This information is intended to assist the environmental professional, but is not necessarily required to qualify for one of the LLPs. The information includes:
- (a) the reason why the Phase I is being performed,
- (b) the type of property and type of property transaction, for example, sale, purchase, exchange, etc.,
- (c) the complete and correct address for the property (a map or other documentation showing property location and boundaries is helpful),



X3. USER QUESTIONNAIRE

INTRODUCTION

In order to qualify for one of the Landowner Liability Protections (LLPs)187 offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"), 188 the user must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by EPA Brownfield Assessment and Characterization grantees. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete.

| | (1.) Environmental liens that are filed or recorded against the property (40 CFR 312.25). Did a search of recorded fand title records (or judicial records where appropriate, seeNote 1 below) identify any environmental liens filed or recorded against the property under federal, tribal, state or local law? |
|---|--|
| | Note 1—In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that environmental liens and AULs be filed in judici records rather than in land title records. In such cases judicial records must be searched for environmental liens and AULs. |
| | (2.) Activity and use limitations that are in place on the property or that have been filled or recorded against the property (40 CFR 312.26(a)(1)(v) and vi)). Did a search of recorded land fittle records (or judicial records where appropriate, seeNote 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filled or recorded against the property under federal, tribal, state or local law? |
| | (3.) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28). Do you have any specialized knowledge or experience related to the <i>property</i> or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business? |
| | (4.) Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29). Link wown. Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property? |
| | (5.) Commonly known or reasonably ascertainable information about the property (40 CFR 312.30). Are you aware of commonly known orreasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, (a.) Do you know the past uses of the property? (b.) Do you know of specific chemicals that are present or once were present at the property? (c.) Do you know of spills or other chemical releases that have taken place at the property? (d.) Do you know of any environmental cleanups that have taken place at the property? (d.) Do you know of any environmental cleanups that have taken place at the property? |
| | (6.) The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31). Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property? 3/8/2017 — Sharon Butts, Director EDC And Bruce Diagnale completed this form. |
| C | 187 Landowner Liability Protections, or LLPs, is the term used to describe the three types of potential defenses to Superfund liability in EPA's Interim Guidance Regards. Criteria Landowners Must Meet in Order to Qualify for Bona Fide Prospective Purchaser, Contiguous Property Owner, or Innocent Landowner Limitations on CERC iability ("Common Elements" Guide) issued on March 6, 2003. |

X3.1 In addition, certain information should be collected, if available, and provided to the environmental professional conducting the Phase 1 Environmental Site Assessment, This information is intended to assist the environmental professional, but is not necessarily required to qualify for one of the LLPs. The information includes:

(a) the reason why the Phase I is being performed,

(b) the type of property and type of property transaction, for example, sale, purchase, exchange, etc.,

(c) the complete and correct address for the property (a map or other documentation showing property location and boundaries is helpful),

¹⁸⁸ P.L. 107-118.

APPENDIX

"E"

Historic Topographic Maps

Trigg County Industrial Park # 3 - Tract 2
International Drive
Cadiz, KY 42211

Inquiry Number: 4854218.4

February 14, 2017

EDR Historical Topo Map Report

with QuadMatch™



6 Armstrong Road, 4th floor Shelton, CT 06484 Toll Free: 800.352.0050 www.edrnet.com

EDR Historical Topo Map Report

02/14/17

Site Name:

Client Name:

Trigg County Industrial Park #:

Ronald Johnson & Associates psc

International Drive Cadiz, KY 42211 24 West Center Street Madisonville, KY 42431

EDR Inquiry # 4854218.4

Contact: Bruce Dipasquale



EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Ronald Johnson & Associates psc were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

Coordinates:

P.O.#

Project:

17-029

Tract 2 Trigg EDC

Latitude: Longitude: 36.881038 36° 52' 52" North

-87.748038 -87° 44' 53" West

UTM Zone:

Zone 16 North

UTM X Meters:

433338.44

UTM Y Meters:

4081936.83

Elevation:

518.00' above sea level

Maps Provided:

2013

1981, 1982, 1983

1974

1967

1951, 1953

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2013 Source Sheets



Cadiz



Gracey



Caledonia



Cobb

7.5-minute, 24000

7.5-minute, 24000

7.5-minute, 24000

7.5-minute, 24000

1981, 1982, 1983 Source Sheets



Caledonia



Cadiz



Cobb

7.5-minute, 24000 Aerial Photo Revised 1974

7.5-minute, 24000 Aerial Photo Revised 1981

7.5-minute, 24000 Aerial Photo Revised 1981

1974 Source Sheets



Caledonia



Gracey

7.5-minute, 24000 Aerial Photo Revised 1974

7.5-minute, 24000 Aerial Photo Revised 1974

1967 Source Sheets



Cobb



Cadiz

7.5-minute, 24000 Aerial Photo Revised 1950

7.5-minute, 24000 Aerial Photo Revised 1951

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1951, 1953 Source Sheets



Caledonia

7.5-minute, 24000 Aerial Photo Revised 1949



Cadiz

7.5-minute, 24000 Aerial Photo Revised 1951



Gracey

7.5-minute, 24000 Aerial Photo Revised 1951




Cobb

7.5-minute, 24000 Aerial Photo Revised 1951

SW


S

SE



Ronald Johnson & Associates psc


CLIENT:



SW

S


SE




SW

S

SE





APPENDIX

" F"

City Directories

Trigg County Industrial Park # 3 - Tract 2

International Drive Cadiz, KY 42211

Inquiry Number: 4854218.5 February 16, 2017

The EDR-City Directory Image Report



TABLE OF CONTENTS

SECTION

Executive Summary
Findings
City Directory Images

Thank you for your business.

Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER, IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING. WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

| <u>Year</u> | Target Street | Cross Street | Source |
|-------------|---------------|--------------|---------------------------|
| 2013 | | \square | Cole Information Services |
| 2008 | | \square | Cole Information Services |
| 2003 | | \square | Cole Information Services |
| 1999 | | \square | Cole Information Services |
| 1995 | | | Cole Information Services |
| 1992 | | \square | Cole Information Services |

RECORD SOURCES

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

FINDINGS

TARGET PROPERTY STREET

International Drive Cadiz, KY 42211

| <u>Year</u> | CD Image | Source | |
|-------------|----------|---------------------------|---|
| INTERNAT | IONAL DR | | |
| 2013 | | Cole Information Services | Target and Adjoining not listed in Source |
| 2008 | | Cole Information Services | Target and Adjoining not listed in Source |
| 2003 | (=) | Cole Information Services | Target and Adjoining not listed in Source |
| 1999 | | Cole Information Services | Target and Adjoining not listed in Source |
| 1995 | - | Cole Information Services | Target and Adjoining not listed in Source |
| 1992 | | Cole Information Services | Target and Adjoining not listed in Source |

FINDINGS

CROSS STREETS

Year CD Image Source


ROCKY POINT RD

1992 pg. A6 Cole Information Services

ROCKY RIDGE RD

| 2013 | pg. A2 | Cole Information Services |
|------|--------|---------------------------|
| 2008 | pg. A3 | Cole Information Services |
| 2003 | pg. A4 | Cole Information Services |
| 1999 | pg. A5 | Cole Information Services |
| 1995 | _ | Cole Information Services |

Target and Adjoining not listed in Source



Cross Street

Source

Cole Information Services

ROCKY RIDGE RD 2013

1949 DON BACON

Cross Street

Source

Cole Information Services

ROCKY RIDGE RD 2008

1928 ROCKY RIDGE BAPTIST CHURCH

1949 DON BACON

2368 ELSIE TYLER

Cross Street

Source

Cole Information Services

ROCKY RIDGE RD

2003

2368 FRANCES SIZEMORE

Cross Street

Source

Cole Information Services

ROCKY RIDGE RD

1999

1931 MARY REDD

2368 HERBERT SIZEMORE

Cross Street

Source

Cole Information Services

ROCKY POINT RD

1992

| 146 | ROWLEY, CECIL |
|-----|------------------|
| 206 | LAMB, WILLIE E |
| 280 | JEFFRIES, GERALD |
| 320 | PARROTT, RAY |

APPENDIX

" G "

Resume

Bruce M. DiPasquale

Summary

37 years of experience in management of environmental projects ranging from environmental audits; including ISO 14000 consulting and training, ASTM Phase I and II, All Appropriate Inquiry (AAI), hazardous waste site remediation, groundwater protection plans, site characterizations, corrective action plans, and cost estimates, over site duties of environmental contractors, to environmental permitting of water discharges, wellhead protection plans, mining operations, landfill facilities, Certification for OSHA Hazardous Waste Site Worker 40-Hour training, plus supervisory training.

Education

Graduate Assistant, Western Kentucky University, 1975-1976

B.S., Biology, Murray Sate University, 1975

Publications

Hoyt, R., Allan Watt and Bruce DiPasquale. Kentucky Fisheries Bulletin No. 62.

Professional Experience

1997 - PRESENT - SENIOR PROJECT MANAGER, Ronald Johnson and Associates, PSC.

Responsibilities include client/regulatory agency interactions. Project coordination and management duties encompass the full range of environmental issues, to include ISO 14001 Standards consulting and audits, ASTM Phase I and II environmental site assessments, environmental audits, compliance audits, air quality, water, waste management, underground storage tanks, spill prevention control and containment plans, mining, underground injection control, and biological/wetland evaluations.

1990-1997 - SENIOR PROJECT MANAGER, McCoy & McCoy Environmental Consultants, Inc. /Analytical Management, Inc.

Served as regional office manager. Responsibilities included overall regional management of human resources, equipment, facilities, and client/regulatory agency interactions. Project coordination and management duties encompassed the full range of environmental issues, to include air quality, water, waste management, underground storage tanks, spill prevention J:/dipasquale.doc

control and containment plans, mining, underground injection control, biological/wetland evaluations, environmental audits, and comprehensive site assessments.

1980-1990 - SENIOR ASSOCIATE AND BIOLOGIST, McCoy & McCoy Environmental Consultants, Inc.

Served as regional office manager for MMECI. Managed projects involving air contaminant source permitting, RCRA groundwater monitoring, hazardous waste spills, site assessments, remediation, UST removal, KPDES permitting, bio-monitoring, biological site evaluations, and surface and underground mine permitting. Performed state, regional, and local environmental audits and site assessments in Kentucky, Indiana, Iowa, Illinois, Tennessee, and Washington.

PROFESSIONAL DEVELOPMENT

"RAB certification as Environmental Auditor, 2003 -2005

"ISO 14000 – 36 Hr Advanced EMS Lead Auditor" training. Applied Quality Systems, Inc., Louisville, KY

"Total Quality Management." Tennessee Associates, Inc., Knoxville, TN

"Predictive Index." Mercer - Meidinger - Hansen, Inc., Louisville, KY

"Environmental Audits." Government Institutes. Hilton Head, South Carolina.

Hazardous Waste Site Worker 40-Hour Safety Training.

Kentucky Licensed Realtor

PARTIAL PROJECT LISTING

Badgett Properties - ASTM Phase I Environmental Site Assessment of industrial properties for sale.

Swanson Industries, Inc. – ASTM Phase I Environmental Site Assessment of industrial properties for transfer of ownership.

Pennyrile Area Development District – Pennyrile WestPark Industrial Park – Lyon County Kentucky - ASTM Phase 1 Environmental Site Assessment of 650 acres of agricultural property for transfer of ownership and future industrial development. Project was to determine environmental concerns.

Custom Resins – Henderson, Kentucky – ASTM Phase 1 Environmental Site Assessment of industrial properties for financial considerations.

Old National Bank – ASTM Transaction Screen Process various properties.

Kuttawa Harbor - Underground Storage Tank removal.

Ingram Barge Company - ASTM Phase I and II ESA of industrial properties.

Shamrock Technologies, Inc. - ASTM Phase I and II ESA of industrial properties.

Krueger International - ASTM Phase I ESA of industrial properties.

Economic Development Corp. of Madisonville - Hopkins County - ASTM Phase I ESA of industrial properties.

Anne Shelburne, Atty. - ASTM Phase II ESA of property in Owensboro, KY for future bank location.

Harrah's Entertainment, Inc. - ASTM Phase I & II environmental site assessment of properties for transfer of ownership.

Cole, Moore, and Baker - Site assessment and expert testimony in civil suit of alleged soil contamination.

ABC Bancshares Corp. - ASTM Phase II environmental site assessment of suspected contamination of proposed property for transfer of ownership.

Ellis Estate - Environmental remediation and clean closure of RCRA lead contaminated soils. Kentucky Superfund Branch.

Elkton Die Casting - Phase II Environmental Site Assessment for RCRA and TSCA contamination.

Arms Equipment, Inc. - RCRA hazardous waste clean-up and disposal of fire debris in McQuady KY. Kentucky Div. of Waste Management, Louisville Regional Office.

Elizabethtown Laundry – Dry cleaning solvent underground tank removal and clean closure. Kentucky Superfund Branch.

Merritt Place Development, (H & M, LC). - Closure of abandon solid waste dump site and subsequent residential land use approval in Henderson, Kentucky. Kentucky Superfund Branch.

Coordinated and assisted in the environmental audit of the Unison Transformer Services, Inc. plant site at Henderson, Kentucky prior to plant start-up.

Coordinated closure certification for the USEPA-TSCA closure of Unison Transformer Services, Inc., Henderson, KY. USEPA Region 4.

Julian M. Carroll, Atty. – Provided environmental consulting to legal council opposed to Mid-West Terminal's proposed coal loading facility near Paducah, KY.

Paducah and Louisville Railway, Inc. - Phase I environmental compliance audit of all on-line facilities and record keeping systems associated with various environmental permit requirements.

Deena Products, Inc. - superfund clean up of abandoned cyanide plating waste and contaminated soil.

Ahlstrom Filtration, Inc. - represented buyer's environmental interest of a Georgia Pacific paper plant in Illinois.

K B Alloys, Inc. - represented buyer's environmental interest of a metal alloy processor in Memphis, TN.

K B Alloys, Inc. - Phase II site assessment and PCB remediation of historic spills at an aluminum alloy plant, Malaga, Washington.

WR Grace Co. - assessment of waste pond contamination.

Air Products, Inc. - assessment of contamination from a PCB underground storage tank.

Kentucky Parks Department - assessment of impact to Green River Lake State Park by proposed development.

Venture Mining Co. - Phase I environmental site assessment of mining properties for transfer of ownership.

Mapco, Inc. - represented buyers interest in Phase II environmental site assessment of Andalex Mining Company properties.

J:/dipasquale.doc

4

Reed Crushed Stone, Inc. - represented seller's environmental interest in the third largest rock quarry in the Southeastern United States.

Phase II environmental site assessment and site remediation of PCBs and other organic compounds discovered at an industrial park in Henderson County, Kentucky.

Texas Gas Transmission, Corp. - clean up of contaminated soil at various locations along transmission line in the western Kentucky area.

Douglas Autotech, Corp. – Hopkinsville, KY – ISO 14001 consulting and training for ISO 14001 certification. Responsible for assisting HR Manager, training, auditing, and consulting in all aspects of the ISO EMS standards.

Niles American Wintech – Winchester, KY – ISO 14001 consulting. Conducted environmental compliance audit of their facility for their ISO 14001 EMS procedure.

Buckhorn, Inc. Dawson Springs, KY - ISO 14001 internal auditor training. Responsible for training, at an introductory level, the facilities existing quality auditing team in the ISO 14001 internal auditing requirement as well as the appropriate areas of ISO 14010 and 14011.

Buckhorn, Inc. Shelbyville, KY - ISO 14001 Gap Audit. Responsible for auditing the status of their ISO 14001 implementation efforts and determining additional needs.

Freundberg Nonwoven, Corp. Hopkinsville facility - ISO 14001 internal auditor training. Responsible for training facility personnel in the ISO 14001 internal auditor requirement as well as the appropriate areas of ISO 14010 and 14011. The class time of 24 hours included a review of ISO background information, the standards, auditing problems, practice internal audit, discussion of findings and an informal report to the Environmental Representative.

Federal Mogul, Corp., Scottsville facility - ISO 14001 training and consulting. ISO 14001 consulting and training for ISO 14001 certification. Responsible for assisting EHS Manager, and training, auditing, and consulting in all aspects of the ISO EMS standards. This project is complete and Federal Mogul was certified in May 2002.

Ahlstrom Engine Filtration, LLC, Madisonville facility - ISO 14001 consulting. Responsible for general consulting regarding their in house ISO 14001 efforts.

Grupo Antolin – Kentucky, Hopkinsville facility - ISO 14001 training and consulting. Responsible for training, at an introductory level, the facilities existing quality auditing team in the ISO 14001 internal auditing requirement as well as the appropriate areas of ISO 14010 and 14011. Class time 4 hours.

Plymouth Extruded Shapes, Inc., Hopkinsville facility - ISO 14001 consulting and training for ISO 14001 certification. Responsible for assisting ER Manager, training, auditing, and consulting in all aspects of the ISO EMS standards. Plymouth is expecting certification in 2002. Conducted compliance audit on this facility in October 2002.

Meritor Suspensions Co. Inc., Hopkinsville facility - ISO 14001 consulting and training for ISO 14001 certification. Responsible for assisting ER Manager, training, auditing, and consulting in all aspects of the ISO EMS standards. This facility is certified as conforming to the ISO 14001 standards. Other projects at this facility include SPCC Plans and Haz Mat Procedures.